



PHASE COMPENSATION METHOD AND . Kunimatsu Ref. No. 0941.65732









PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 3 of 19 (312) 360 0080




FIG. 3A

76

40

101




F1G. 4

PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 4 of 19 (312) 360 0080

0 0 √MOX $\overline{\mathsf{O}}$ 110 78-


PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 5 of 19 (312) 360 0080

F16.5




PHASE COMPENSATION METHOD AND . . . Kunimatsu Greer, Burns & Crain, Ltd. (Patrick Burn. Ref. No. 0941.65732 Sheat 6 of 19 (312) 360 0080

FIG. 6



PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 7 of 19 (312) 360 0080

FIG. 7



PHASE COMPENSATION METHOD AND . . . Kunimatsu Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65732 Sheet 8 of 19 (312) 360 0080

FIG. 8






FIG. 9




PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 9 of 19 (312) 360 0080

FIG. 10



PHASE COMPENSATION METHOD AND . . . Kunimatsu Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65732 Sheet 10 of 19 (312) 360 0080


F16. 1






PHASE COMPENSATION METHOD AND . . . Kunimatsu Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65732 Sheet 11 of 19 (312) 360 0080

FIG. 12




PHASE COMPENSATION METHOD AND . . . Kunimatsu Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65732 Sheet 12 of 19 (312) 360 0080

FIG.13




PHASE COMPENSATION METHOD AND . . . Kunimatsu Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65732 Sheet 13 of 19 (312) 360 0080

FIG.14




PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 14 of 19 (312) 360 0080

FIG. 15




PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 15 of 19 (312) 360 0080




PHASE COMPENSATION METHOD AND . . . Kunimatsu
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65732
Sheet 16 of 19 (312) 360 0080

FIG.17



PHASE COMPENSATION METHOD AND .
Kunimatsu
Greer, Burns & Crain, Ltd. (Patr
Ref. No. 0941.65732
Sheet 17 of 19 (312) 360 0080

FIG. 18



Ref. No. 0941.65732 Sheet 18 of 19 (3 (312) 360 0080

FIG. 19




FIG. 20




FIG. 21




FIG. 22

